



**Control Box**

WIRING DIAGRAM COVERS  
ECM 1.0 HP MOTORS

**LEGEND**

PURP = PURPLE	GRY = GREY
YEL = YELLOW	GRN = GREEN
BRN = BROWN	BLK = BLACK
WHT = WHITE	PNK = PINK
BRN = BROWN	RED = RED
ORN = ORANGE	BLU = BLUE
HUM = HUMIDISTAT	
CLO = COMPRESSOR LOCKOUT	